

33348

Ms A 3217

REPORT ON ANNUAL LOAD LINE SURVEY.

Official Number 161299. Port of Registry London

Dates of Survey 23024/4/40.

Date of last Load Line Survey

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
INCLUDING SMALL HATCHWAYS.			
board deck.			
ys and stiffeners...			
...			
...			
...			
... (hatchway)			
...			
... ttings			
... ing spares, adequate ?)			
structure decks, including raised			
nd stiffeners	Good		
...	Good		
...	✓		
...	Good except for	No 1.-16: No 2-18:	} 24/4/40.
...	2- Good	No 3-3: No 4-23:	
... (hatchway)	Good	No 5-2: T.O.-1.	
...	Good	to renew.	
...	Good		
... ing spares, adequate ?)	Good — yes.		
structures not intact or not protected			
ing appliances.			
...	Good		
...	Good		
...	✓		
...	Good except for	No 1-1: No 2-3:	} 24/4/40.
...	Good - 2	No 3-3: No 5-2.	
... (hatchway)	Good.	to renew.	
...	Good - Yes.		

ry should be

overs, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).

ENGLAND.)

Paragraph 117 (i)).

© 2021

Lloyd's Register
Foundation

0-5397-005402-0063 1/2

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	} <i>found</i>		
Closing arrangements			
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	✓		
Closing arrangements			
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	<i>found</i> ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	<i>found</i> ✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	} <i>found</i> ✓		
Skylights, their fastenings, covers and lashings			
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	<i>found</i> ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	<i>found</i> ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	<i>found</i> ✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	✓		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	good ✓		
Bridge, fore end... ..			
Bridge, after end			
Poop			
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	good ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
	good ✓		
18. GUARD RAILS			
	good ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	✓		
20. LIFELINES (fittings and material)			
	✓		
21. FREEING PORTS in T. Well.			
Shutters	good ✓		
Protection bars			
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	✓		
24. LOAD LINE MARKS			
	verified & found correct.		

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circulars and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
all	R. Webster	Liverpool	24/4/40

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor R. Webster Place Liverpool Date 24/4/40

Signature R. Webster

Date 24/4/40


† Insert "all" in case of a complete survey.

5000
29/4/40

Fee £ 5-1

Number of Visits 2

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register
Foundation