

"ARMADALE"

It appears from the reports that
to complete the Special Survey on the hull,

Nos. 3, 4 & 5 holds, Nos. 3, 4 & 5
D.B. tanks and deep tank, also forward rigging, require
to be examined, Nos. 3, 4 & 5 D.B. tanks, deep tank
and oil bunkers tested. *W. J. [unclear]*

In addition, defective shell rivets
in No. 1 lower hold (s.s) require to be renewed and
indented plating starboard side forward permanently
repaired.



Ed Mo
2021
12-11-41

Lloyd's Register
Foundation

005397-005402-0083