

Received from Chief Ship Surveyor

14 JUL 1959

NAME

"SAGAR PRABHA"

REPORT

Bom.

No. 14202

VC

Existing Conditions of Class:

SUBJECT to indented shell plates
in 'G' and 'H' strakes (s.s.) to shell plates E.5 (p.s.a)
B.1 and C.1 (p.s.f) being specially examined and dealt
with as found necessary by the Special Survey.

Appendix. (~~As before~~ None)of Present Survey: (Afloat ~~and in dry dock~~)

Examination of temporary repairs.

Foundation:

SHELL

SUBJECT as above, and to/riveting in No.4
D.B. tank (p.s) being specially examined and
dealt with as found necessary by the next
drydocking.

As now. SUBJECT.



© 2021

Lloyd's Register
Foundation

005397-005402-D17A