


"SAIDJO"

For full particulars of this case see Ship Reports Department Endorsement of 14.7.58 and Ship Research Department Memo of 9.9.58.

SUBMITTED the Surveyors be informed in accordance with the Ship Research Department Memo of 9.9.58. In connection with the internal structure referred to therein the under-noted plans marked thus () should be readily dealt with by them, but for their general guidance in dealing with same they should be advised that where the diminution of the internal and minor structures is approximately 30% of the original thickness it should be renewed.

Further, IT IS SUBMITTED duplicate copies of the under-noted plans should be returned to the SINGAPORE Surveyors for their information in dealing with this case.

(Structure in Internal Tanks.)
Shell Plan.
(Longitudinal Bulkhead Trunk) and Main Deck.
(Tank Top Bulkheads and Internal Structure etc.).


11.9.58.



© 2021

Lloyd's Register
Foundation

005397-005402-0210