

Blk.

by Chief Ship Surveyor Received from Chief Ship Surveyor

S NAME "SAIDJA" REPORT Sng. No. 12562

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/52.)

There is a S.R.L. Appendix Note.

A SPECIAL SURVEY (D) becomes due 12,58.

The SINGAPORE Surveyors report (3,58), this ship examined afloat and in dry dock and the cargo tanks etc. generally examined internally in accordance with Circular No.2106 with a view to ascertaining the anticipated repairs at the Special Survey.

The thicknesses of shell, deck and cargo tank internals etc. as ascertained by drilling are embodied on plans attached to this report for our consideration.

Wear and tear repairs effected to rudder, shell plating and cargo tank internals etc.

The Owners, through the Singapore Surveyors, request recommendations for repairs in connection with the following proposals - (a) A Special Survey (D) to maintain her present class i.e. #100A "For Service in the East Indian Archipelago" "Carrying Petroleum in Bulk" (b) A SPECIAL SURVEY (D) necessary to amend the ship's class to that previously i.e. #100A "Carrying Petroleum in Bulk" - refer Singapore Surveyors' letters dated 24.4.58 & 30.6.58 and Owners' letters dated 24.4.58 & 24.6.58. In connection with this matter see also Ship Research Endorsement dated 11.7.58.

IT IS THEREFORE SUBMITTED this ship is eligible to remain as now classed with record of 'DS 3,58' assigned as recommended.

DS 3,58

S.R.L. APPENDIX NOTE

Intents in shell plates D.8 (s.s.) and E.7 (p & s.f.) and forecastle side plating etc. (s.s.). (Ship to be drill tested by 12,58).

MR. G. BUCHANAN 'AFTER COMMITTEE.



© 2021

Lloyd's Register Foundation

005397-005402-0212

Both Ts 2.58

DRILLING PLANS

Handwritten initials/signature

JAN 1958