

19 APR 1960

SHIP NAME

"SENZAN MARU"

REPORT

Smk.

No. 1571

Standing Conditions of Class:

SUBJECT to set in shell plates E.6 & 8 and structure in way (p.s.a) being specially examined and dealt with as necessary also to permanent repairs to (fractured) shell plates F.16 and D.16 in way of No.1 hold (p.s.), at the next drydocking.

ACTION is DEFERRED for examination in dry dock after contact with submerged object.

L. Appendix. (As before ~~or None~~)

Area of Present Survey: (Afloat and in dry dock)

Docking: Permanent repairs to part deferred item as above. *WAT. y.*

Recommendation:

SUBMITTED record of 'DS 3,60' be assigned, subject to set in shell plates E.6 & 8 and structure in way (p.s.a) being specially examined and dealt with as necessary next Special Survey, but without other condition.

DS 3,60 Subject, Amended,
Without.

~~DELETE FROM S.R.L.
Drydocking(sub.obj.).~~

~~IN S.R.L. APPENDIX.~~

~~Keel and bottom plating set up.
Forecastle plating etc. indented.~~



© 2020

*4^e
7/4/60*

Lloyd's Register
Foundation