

Lloyd's Register of Shipping,

14, Cross-shore Street,

Greenock, 28th November, 1942.

Reference

Dear Mr. Ritchie,

With reference to Greenock Report No. 21932 on the "EMPIRE MIGHT", it is stated that the steam pipes are "BESSEMER" - this is an error, as all the steam pipes with the exception of the steam to deck service, oil fuel discharge to boilers and several of the steam pipes to auxiliaries 1.11/16" and under are of Open Hearth Steel. I shall be glad if you will make the necessary correction on the Report.

With regard to Greenock Report No. 22085 on the "EMPIRE WISDOM", the only "BESSEMER" pipes fitted are steam to refrigerating machinery, steam to deck service and from the auxiliary steam range to several of the pumps.

Kind regards,

Yours sincerely,

Charles J. Hunter

G. D. Ritchie, Esq.,
WOKINGHAM.

noted by
FJ 30/11/62.



© 2020

Lloyd's Register
Foundation