




Lloyd's Register of Shipping,

14, Cross-shore Street,

Greenock, 22nd August, 1935.



Reference

Dear Sir,

With regard to the first entry report No. 19990 on the S.S. "MARWARRI", I regret that the thickness of the second deck in way of the bridge has been inadvertently reported as approved and not as fitted in the vessel. The thickness of the deck plating should be .40 and the deck stringer should be 54 x .44,

Also the size of the deck beams as given in the report are as fitted at 27" spacing, and the size at 30½" spacing is 9 x 3½ x .38 B.A.

I am therefore returning the classification certificate and would be glad if these could be amended accordingly.

I am, Dear Sir,

Yours faithfully,

Kenneth Inglis

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

005436-005442-0026

Referred to the Chief Ship Surveyor,

23 AUG 1935

30.12.35

© 2020

Lloyd's Register
Foundation



GRAPHIC ADDRESS