

"SHILLONG"

Req. 13. (Received at London Office..... 19.....)

No. 5806 Port Newcastle Date July 8th 19 46

we request that the Refrigerating Machinery and Appliances of the ~~Motor~~ ^{Steam} Ship building by Messrs Vickers Armstrongs Ltd for P.T.O. Steam Navigation Co. Ltd

Builders' Yard No. 104 may be specially surveyed during construction with a view to the notation

*RMC (in red) (i.e., Refrigerating Machinery Certificate) being made in the Register Book.

The vessel is.....intended for Classification in Lloyd's Register.

we hereby engage to pay the established scale of fees, or any variation therefrom which has duly notified.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connection with the above services, they are to be defrayed by the parties interested.


This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Manufacturers of Refrigerating Machinery Messrs J & C. Hall Ltd, Dartford, Kent.

Signature.....

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.



NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Lloyd's Register
Foundation

005453-005461-0037

and manhole doors of tanks yes Are insulated plugs fitted to ventilators yes cargo ports yes

In the insulation of the lower hold floor and tunnel top in areas of the hold being protected yes if so, how 3/8" mineral

COR
LA
OR
RA
OR
AAC
IAN.
ABC
RAN
ORA
3"
6"
VEL
GRA
u
3/8" mineral