

2m.11.28.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Paul S.C. "COMEDIAN"

Report

GLS

No. *49728.*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1st Entry

When due

old Rules.



+100 A.I. (Ptl)

2 D's (Ptl)

Cell DB 334' 1122t, Dta 30' 762t, FPT 76t, APT 26t.

FK 7 BH to Upper D^K, 1 BH to 2nd D^K, Cem, Lloyds A & CP.

P 34', B 124', F 40'



© 2021

WJH
24.10.29.
P.T.O
Lloyd's Register
Foundation

005453-005461-0148 1/2

See "COMEDIAN" GLS R/L- NO 49428.

See letter.

It is concluded the size of the frames amidships ~~is~~ as approved, and that the thickness of the midship bulkhead plating in hold & thickness of the upper deck stringer angle in wells are as approved, but the Surveyors should be requested to state if this is so.

Lf 28/10/28



© 2021

Lloyd's Register
Foundation