

Chief Surveyors 20.8.17

Received from Chief Surveyors

SHIP'S NAME

Sheels Kiowa

Report

Her

No. 101.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

When due


Cargo battens are not fitted.

❖ 100A.1. (Steel)

1 DK (Steel)

Cell D.B. 222 478L. F.P.T. 67L A.P.T. 77L

FK. 4BH. Cen. at CP. P 27 B 64 F 26



The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

M
21.8.17

*The Surveyors should be informed it is
concluded the top top plating in way of hatchways
is as approved & has in sister vessels.*

*They should also be informed that the
spacing of the bridge & fore-castle beams has
been omitted in their report.*



© 2020

Lloyd's Register
Foundation

005470-005479-0154

& thickness

26