

end of the tube shaft

Length of Bearing in Stern Bush next to and supporting propeller
Material *Brass* whether Moveable *No* Total

G. Sandale

It is concluded that the
Main Boiler Safety valve area given
in the Report is for one valve, not
one set of valves but this should
be confirmed & the Surveyors
requested to state the thickness of
the screw shaft liner in way of the
bearing.

Mr. 20/9/29

005480-005488-0116

compartment to another

is not subject to same treatment

Lloyd's Register
Foundation