

Caripiteno

Jan. 21/61.

It is submitted that before this case receives consideration the Surveyors' attention should be drawn to the Secretary's letter 'E' of 8-10-30.

It would appear from their report that only two bi-ge pumps are fitted, viz:- one on the main engines and one independent; but they should be requested to state what further provision has been made to comply with the above letter.

L 12/6/34



*[Handwritten signature]*

24  
12/6/34

Lloyd's Register  
Foundation

005524-005536-0113