

COPY. COPY

# Lloyd's Register of Shipping.



Port Baltimore, Maryland

November 28th, 1941

**This is to Certify** that

Mr. G. Cowin

the undersigned Surveyor to this Society did at the request of the Owners' Representative survey the Steel Screw Steamer

"MARISA THORSEN"

4536 tons gross of Panama for the purpose of ascertaining the extent of damage stated to have been sustained through encrusting ice on the 31st of March 1941 whilst on voyage from Petsamo to Murmansk.

On examining the vessel on dry dock at the plant of the Maryland Drydock Company on 28th November 1941 the undersigned

Found

Recommended

Shell Plating, Forward

Shell plates F 2 and 3  
Port and Starboard Sides  
scored

To be renewed.

Further recommended the Fore Peak Tank be filled to test the renewed plates and the renewed plating in No. 1 Hold be hose tested, and all removals be replaced and where damaged (in course of above repairs) repaired or renewed as necessary, and that the work be suitably coated upon completion.

These recommendations made so as to place the vessel in the same good and efficient condition as before the damage was sustained.

(Signed) Mr. G. Cowin  
Surveyor to Lloyd's Register of Shipping

\$ 25.00  
PS 4.50  
te 10.00

© 2020  
Foundation  
005524-005536-0170

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."