

2m.11.35.

1

'21 JUL 1937

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME "AKUNA" Report Lon. No. 103375a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

When due

The 2nd S.S.No.3 became due 1,37.

*As due 5-39
facts held*

The class is subject to corrosion of the steel upper deck plating below the sheathing being dealt with at the Special Survey.

The Melbourne Surveyors now forward a letter from the Owners to the effect that they have decided to withdraw this vessel from the Society's class.

It is submitted the class of the vessel be withdrawn and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class
Insert ...



© 2021

Lloyd's Register
Foundation

005635-005643-0077