

Compulsory

Rpt. 12.

copy
FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port Bombay (When received in London Office)

Vessel's Name Badora

Official No. 131913 No. in Reg. Book

Port of Registry (For Foreign Vessels) Bombay

Iron or Steel Steel State whether Classed by Lloyd's Register Yes

Name of Owners Rivers Steam Nav. Co. Ltd Date of Verification Oct 9th 1914

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line 2 ft. 3 ins.

From centre of disc to top of statutory deck line }
at awning or part-awning deck . . . } ✓ ft. ✓ ins.

Fresh water line above centre of disc . . . 2 ins.

Indian Summer line above centre of disc . . . ✓ ins.

Winter line below centre of disc . . . ✓ ins.

Winter North Atlantic line below centre of disc ✓ ins.

Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side }
at main, spar or upper dk. 1 ins.
at awning or pt.-awning dk. ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Signed) John H. Mackenzie Surveyor.

(To be filled up in London Office.)

Statement No 23837 Date of Committee's Minute 21.7.14

Moulded Depth for record . . . 9 ft. 6 ins.

Freeboards compared and found correct by date 14.11.14


Is fee paid? Al a/c Form for Certificate A

Instructions date

Certificate written Noted for posting

Im.7,14.—T.

*Classification A1 Boasting Bunsal & Chittagong
Conditional on the above free boards.*



© 2020

Lloyd's Register Foundation

005791-005810-0246

Special Survey Fee.... £ 12 : 12 : -

Received by me,

Certificate to be sent to GLASGOW