

- 4 MAR 1942

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME BONIFACIO REPORT Lon No. 109167a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Screwshaft Survey became due 3.41.

The Marseilles Surveyors write they are informed by the Owners that they have decided to withdraw the class of this vessel from the Society's Register Book.

It is therefore submitted the class be withdrawn from the Register Book and Three Dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class

Insert ...

PLATING TO BE DRILLED when
vessel is 24 years
or at next Special Sur
thereafter



© 2021
Lloyd's Register
Foundation