

Rpt. 8.

(Received at London Office

DISCLOSED

SECTION No. 230
No. 111505

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....19.....

When handed in at Local Office.....19.....

Port of LONDON

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

56601

on the Wood, Iron or Steel ss. "DARICA"

(No. of Visits.....)

TONNAGE :-

GROSS

672

UNDER DK.

550

NET

764

Built at

Port of London

By whom

P. J. R. (Port of London)

When

YEAR.

MONTH.

11

Owners

Turkish Government

Owners' Address

(If not already recorded in Appendix to Register Book).

Managers

Port belonging to

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D Bor D Ba

feet; uE & B.

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Report, No.

871

Port Adm.

al Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the cement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. Also the dates and initials of any letters respecting this case.

page cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft. ins.

Was a damage report made by anyone else? if so, by whom?

RS, OR EXAMINATION AS PER RULE, FOR

RY OF DAMAGE REPAIRS :-

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

Renewed ...

Removed and Fair'd or Repaired

Fair'd or Repaired in place ...

CONDITION OF THE

of Decks

Fastenings

Plating

in way of sidelights

Frames

inals

ses.

Bottom Plating

Tanks been examined internally?

Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

(State if examined.)

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained
(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diamr.

(on board.)

" Rule length size

Chain Locker

Hawsers & Warps

Standing and Running Rigging

Sails

eral Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Sect. on 29) £

Special Damage or Repair Fee (if any)

(per Sec. 29)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

19

Received by me,


19

Committee's Minute

Character Assigned

See minute 4.8.44

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register
Foundation

006258-006271-0135