



**GENERAL REMARKS** (State quality of workmanship, opinions as to class, &c.)

These boilers have been constructed under Special Survey and in accordance with plans approved July 18-1917. The workmanship and material are both of good quality. The steam drums and sections have been tested by hydraulic pressure to 400 lbs per sq inch, and found tight and sound. They have now been despatched for fitting aboard. To complete the survey, the boilers to be re-erected on board and tested by hydraulic pressure. All mountings to be examined and fitted. Safety-valves to be adjusted under steam.

Philadelphia

Boilers erected on board, mountings examined and fitted, hydraulic test of 400 lbs applied and safety valves adjusted under steam to 200 lbs.

Certificate (if required) to be sent to  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	:	:	When applied for,
Special .. .. . £	:	:	.....19.....
Donkey Boiler Fee .. .. £	:	:	When received,
Travelling Expenses (if any) £	:	:	.....19.....


Committee's Minute

Assigned

New York SEP - 9 1919

See Phil Rpt No 3390

Alexander Macwall  
Engineer Surveyor to Lloyd's Register of Shipping.



Blellock

Lloyd's Register  
Foundation

S/S  
 Rpt.  
 Por  
 No.  
 Reg.  
 Own  
 Yard  
 DES  
 Dyn  
 ati  
 Cap  
 Wh  
 Pos  
 Pos  
 de  
 5  
 If  
 If  
 Ar  
 Ar  
 A  
 To  
 A  
 B  
 C  
 D  
 E  
 F  
 G  
 H  
 I  
 J  
 K  
 L  
 M  
 N  
 O  
 P  
 Q  
 R  
 S  
 T  
 U  
 V  
 W  
 X  
 Y  
 Z  
 DE  
 M  
 B  
 L  
 C  
 DE  
 #0  
 #1  
 J  
 A  
 A  
 H