

14 MAY 1941

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "DENBYDALE" Rpt. L.A. No. 7523

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.") Extract from Sub-Committee's Report, 24/5/92

Subject as per Lls. 62410 (78)

The Surveyor appointed by Lloyd's Agents at PORT-OF-SPAIN reports this new tanker examined afloat and on account of leakage a number of rivets overhauled and some caulking made good.

In No. 9 starboard wing tank, leakage through the shell at the lower stringer was temporarily dealt with by fitting a cement box secured to the framing.

The Surveyor recommends the vessel as being fit to continue her voyage.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject to the temporary repairs to No. 9 starboard wing tank being further examined on vessel's arrival this side.

has above

As Now, Subject, etc.



© 2021

Lloyd's Register
Foundation

006601-006613-0159

r, or
state
fitted

i, Yar

tion, h
late i
ment

ors, N

s (ste

length

Rule

n Lock

sers &

standing a

Sails