

DISCLOSED SECTION.

226

(Received at London Office)

No. 1139155

Rpt. 8.

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. Survey held at... Date, First Survey... Last Survey... 19... (No. of Visits...)

21531 on the Wood, Iron or Steel 85 "CHERBOURG"

TONNAGE: Built at Aberdeen By whom J Lewis & Sons Ltd When 1921 MONTH 1

GROSS 462 Owners Soc Maritime de Transport & de Owners' Address Transit (If not already recorded in Appendix to Register Book)

UNDER DK. 304 Managers - Port belonging to (French)

NET 189 Managers - Port belonging to (French)

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell/Dor/Da... feet; uE & B... feet; f... feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity... tons. FPT... tons; APT... tons; MT... feet... tons. } CHARACTER. \* for Special Survey. Date of last Survey and of Periodical Surveys.

Only alterations in the existing records of tanks should be inserted. N.B.—All alterations in the existing records should be underlined.

Last Report, No. 48 Port Dpe

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ... ..								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	Engine Room Skylights
Inner Bottom Plating	Coal Bunkers, Openings, Covers, &c.
Have the Tanks been examined internally?	Oil Bunkers
Have the Tanks been tested?	Scuppers
	Cargo Hatchways
	Hatches
	Planking
	Caulking
	Treenails
	Breasthooks & Stemson
	Transoms, Pointers & Crutches
	Timbers of Frame at openings
	" " at other places
	Stringers, Clamps & Shelves
	Salting (State if examined.)
	Copper, or Y.M. (State if on Felt.) When fitted, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed.)
	Equipment letter
	Anchors, No. of
	Cables (State if now ranged)
	" length mean diamr. (on board.)
	" Rule length size
	Chain Locker
	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

FRI, 19 JUL 1946

Committee's Minute... Character Assigned... Withdraw class & insert (...)

Surveyor to Lloyd's Register of Shipping. Special General Committee Thursday, 25th July 1946. Lloyd's Register of Shipping. Classification Committee's decision confirmed.

70774  
19 JUN 1946  
- 3 JUL 1946

If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to 006705-006722-004