

Lloyd's Register of Shipping,

5, Alexandra Buildings,

REFERENCE

Hong Kong, 4th. March 1939.

LLOYD'S REGISTER
Received
14 MAR 1939
And.
LONDON

Dear Sir,

With reference to the Electric Installation Report on the M.V. "ANTONIA" Report No.8301, we have to state that the circuit breaker with overload and reverse current trips had not arrived in the Colony before the vessel was ready to sail and as the vessel was urgently needed fuses were fitted as a temporary measure.

The breakers are due to arrive on the 15th. instant and are being sent to Manila for installing and should be fitted by the end of the present month. Manila Surveyor advised.

We are, Dear Sir,

Yours faithfully,



For The Surveyors.

The Secretary,

LONDON.



© 2021

Lloyd's Register
Foundation

006749-006759-0010

Received by the Chief Engineer, 2nd March 1939

