

Received by Chief Ship Surveyor 28.10.18

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheess Warlimon

Rpt.

10pl

No. 15558

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

72

Depth "d"

20.7

Framing: Table No.

3 page

Description

Bulk Angle as approved

Longitudinal No.

23832

Proportions

Length

= 10.

Depth

Bridge

Deck

Sheerstrake

as approved.

Downton pump & Kedge Anchor dispensed with as approved in Standard Vessel.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100A.1 (Steel) as recommended.

1.07.

Cue 5.13 284' 6995. F.P.T 1365. G.P.T 1415

F.K. 734 pl. 2m Llydasep. P 33. B 100 F 28'

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

006749-006759-0142