

4/

COPY

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port LONDON17th July, 1953.

This is to Certify that I have

Surveyed <sup>Part</sup> ~~the Boiler and~~ Machinery of the S.S. "PROSPECTOR"  
 6165 tons gross of Liverpool on 6.7.53, and subsequently, whilst  
 in dry dock and afloat at Tilbury Dock for Docking, TSCL and  
 damage stated to have been sustained as the result of contact  
 with T.S.S. "CHUSAN" near South Goodwins on 12.6.53,


and that I have transmitted to the Committee of Lloyd's  
 Register of Shipping, London, a Report stating that all  
 recommendations made by me in connection therewith have  
 been carried out to my satisfaction, and that I have  
 Recommended that the record of \* LMC be retained with  
 fresh record of TS CL 7, 53.

be made in the Register Book in the case of this vessel.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register  
Foundation