

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10/6/27 When handed in at Local Office 10/27 Port of Newcastle-on-Tyne

No. in Reg. Book 50943 Survey held at South Shields Date, First Survey 7/6/27 Last Survey 7/6/1927

TONNAGE Built at Greenock By whom Scottish Concrete Ship Co. Ltd. When 1919 12
GROSS 705 Owners Crite Shipping Co. Ltd. Owners' Address
UNDER DECK 655 Managers Steep & Leghinton & Co. Liverpool Port belonging to London
NET 658

Surveyed Afloat or in Dry Dock? Dock Name of Dock Higham & Co. Ltd. Destined Voyage Spain
WB=CeMdBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER For Special Survey, Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.B., if any).
T A 1 12-19 T D B 12-19
Coasting Great Britain & Ireland (Except West Coast, Cork to Pentlands Firth) and Continent—From Great to Hamburg. Subject to Annual Survey Experimental

Report, No. 17610 Port Juk.

1 Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from repairs due to other causes; repairs being detailed in the body of the report, should be summarised in the form shown below. Whenever the condition of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose and to whom and why they were declined Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR DOCKING.

Vessel examined in dry dock. Deck examined. Cowlex Moulding on Stem repairs & cement in way renewed as necessary. Cement in food order. Understood that the Vessel is being sold to the same owners as the concrete barge "Crite" and to be towed to Spain. Newcastle Report No. 81443 (on barge "Crite")

DAMAGE REPAIRS:—	Shell Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
... Paired or Repaired								
... repaired in place								

State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet). When put on, Month Year
State if Tanks now tested	Engine Room Skylights	Boats
Bulkheads	Coal Bunkers, Open'g Lids, &c.	Masts, Yards, &c.
Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Rudder	Hatches	Equipment letter
Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Windlass	Caulking ditto	Cables (State if now ranged)
Have Pumps now been examined and found efficient?	Treerails ditto	„ length (on board) size
Have Sluice Valves now been examined and found efficient?	Breasthooks & Stomson ditto	„ Rule length size
Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	
	Stringers, Clamps & Shelves ditto	
	Salting ditto (State if examined.)	

Observations, Opinion as to Class, Recommendation, &c.:—
Whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey," "to remain as classed and to have record of survey, 1, 2, 4, and the notations of ss No. 1-24 and ptND24, &c."

Annual Survey has not been carried out at this time and it is that the Vessel is to be towed to Spain, this report is forwarded for information of the Committee

Fees applied for, £ 19. Received by me, £ 19.

Minute TUES 14 JUN 1927
Assigned Express class with a red line

Surveyor to Lloyd's Register of Shipping. Special General Committee Thursday 16th June 1927. Lloyd's Register of Shipping's Classification Committee's decision confirmed.

1810 96600-006796-0181

Is Certificate required? If so, to be sent to