


Further, since the sea suction in the pump room have

HERE.

As the Owners apparently require a Load Line Certificate to be issued by the Society, the Freeboard Dept should be informed as soon as possible what the Committee's decision regarding class is, so that further instructions regarding freeboard may be sent to the Surveyor

SR

15.12.49



© 2021

Lloyd's Register
Foundation

006747-006808-0102