

Ship

extent of Examinations and subsequent repairs should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any Letters

m.s. "ABERCRAIG"

This vessel became due for Modified Survey of Oil Engines and Screwshaft Survey at the end of October last and in reply to enquiry the Dundee Harbour Trust now say that in accordance with the usual practice of their Trustees they do not intend to keep this Tay Ferry in classification seeing that for passenger certificate purposes an Annual Survey under the Ministry of War Transport Surveyor is obligatory.

It is submitted the vessel's class should be withdrawn from the Register Book and three dots (...) inserted in lieu thereof at the Owner's request.

29th January, 1942.



© 2021

Lloyd's Register
Foundation

006797-006908-0219

rt, and it is hoped to have every thing completed and of service about the

assigned
now ver

r Y.M.
to if o
ed, M

Yards,
on, how
to if re
ent lett

No. of
tate

gth...
(on t

le leng
oker...

& W
and

el in the Reg