



Lloyd's Register of Shipping.

95, Bothwell Street, Glasgow, C.2.

3rd March, 1939.

Dear Sir,

In reply to your letter of the 1st instant in regard to Glasgow Report No. 60740 on Cochran Boiler No. 14212, intended for a Ferry building by Messrs. Fleming & Ferguson, Ltd., I beg to acquaint you that the Surveyor states that the longitudinal joint in the shell is single riveted.

He regrets that through an error double riveting was inserted in his report.

I am, Dear Sir,

Yours faithfully,

J. H. Warlow

Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

006797-006808-0227

Angles

Bottom

DOUBLE BOTTOM.

ROOF DECK, ANGLE, L. OF

Spacing

Referred to the Chief Engineer Surveyor

Referred to the Chief Engineer Surveyor

N.B.

4 MAR 1939

L.H.

Division Committee.
Secretariat to the

Division Committee.

Home Intelligence

I am, Dear Sir,

Enclosed are inserted in the report.

He reflects that although an error, complete

is single valued.

The following error that the Commission found in the report
measures. According to the Commission, 1939. I refer to the report of the

Commission Report No. 1437, presented for a really serious

the Commission in regard to the Commission Report No. 1437 on

in regard to the report of the

the report, 1939.

© 2021

Lloyd's Register
Foundation