


to U.S. Dept.

Motorship "DEMOCRAAT".

At their meeting on Friday, the Classing Committee asked to be advised of the attitude of the other Classification Societies in the supply of a second independent power pump and auxiliary air compressor. They appreciate that the Germanische Lloyd did not require it, as we do, but are anxious to know whether the British Corporation would insist upon it.


16th December, 1946.



© 2020

Lloyd's Register
Foundation