

72 OCT 1945

"EMPIRE ANNAN" (ex "Masuren").

Mdb. 17917.

A General Examination has been held on the machinery of this ex German vessel without opening up any parts of main engine and the screw shaft has not been examined. *See correspondence.*

BS held. Superheater safety valves remain to be readjusted.

Machinery found satisfactory under working conditions.

It is submitted the vessel is eligible for the Record Examined L.R. 9.45, BS 9.45 (230 lbs) subject to the superheater safety valves being adjusted. *to the screw shaft being examined at first opportunity*



Lloyd's Register
Foundation

006845-006856-0109

at next dry docking, and to permanent repairs to shell (s.s) in way of No. 2 hold and superheater safety valves being adjusted at