

In case of donkey boilers, state whether steam from main boilers can enter the donkey boiler *See Ros Hk 27/7/25.* **No Donkey**

s/s. "Battannic"

It is submitted that the Rotterdam
Surveyors be requested to state the area
of the main safety valves, which has been
omitted from the report.

Lr. 17/7/25

12.5.0"

See Ros Hk 27/7/25.

W.D.
17/7/25

Lloyd's Register
Foundation

007078-007087-0050 by 1

End plates in steam space: Material *✓* **1 M. Steel** Tensile strength **41" 40 KG** Thickness **50 mm**