

LIST OF MACHINERY SPARE GEAR.

Main Motors.

- 1 Propeller,
- 1 Tailshaft
- 1 set of coupling bolts for Intern. Shaft
- 1 " " " " " Crank "
- 1 cylinder cover complete with valves, seats, springs &c.
- 2 complete starting valves,
- 8 discharge valves with 4 seats,
- 1 complete suction valve,
- 2 complete safety valves,
- 8 Pulverizers complete,
- 4 Needle valves for pulverizers & 4 seats,
- 1 set of bolts for cylinder covers,
- 1 piston complete with rod and studs,
- 4 sets of piston rings,
- 2 main bearing brasses and 4 bolts and nuts,
- 2 bottom end brasses and 4 bolts and nuts.
- 2 top end brasses and 4 bolts and nuts,
- 4 pads for Mitchell Thrust block,
- 2 sets of fuel pump working parts,
- $\frac{1}{2}$ set of valves for main compressor,
- 1 compressor shaft main bearing brass with 2 bolts & nuts,
- 1 " bottom end brass with 2 bolts & nuts,
- 1 " top end brass,
- 1 set of piston rings for compressor,
- ~~1 set of springs for compressor,~~
- 1 set of springs for compressor safety valves,
- 1 coil for compressor cooler,
- 1 set of valves for bilge pumps,



© 2020

Lloyd's Register
Foundation