

Im. 12/20.

1

Wise 6/11

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stal S.S. MANELA*Report *Jo*No. *41119***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

✱ 100. A-1. (Stal)

2 Dks (Stal - utaks)

All IB 419' 1550t, FPT 124t, APT 60t

FK, 9BH, Ann, Rlyths A. CP, P44' B161' F42'

Date of build. 4.21.



© 2021

Lloyd's Register
Foundation

007528-007536-0236

and way or Long Bridge

Shoaling

54

54

Angles on ditto, No.

breadth & thickness