

Received by Chief Ship Surveyor

Received from Chief

TELETYPE NAME Stl. Tr. s.s. "MADIRA".

Rpt. 11db.

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Comm.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 21/5/92.)

of Survey

The class of this vessel is subject to damage through striking a quay being permanently repaired at the Owners' convenience.

The Middlesbrough Surveyors now report the vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

The Surveyors recommend that an indented plate on port side be dealt with at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed with record of survey 9-15, subject as recommended and as above.

100 A1

9.25 Mdb.

The fitted for oil fuel etc.

7.10.25.

It is concluded the freeboard is marked in accordance with the assignment, viz 8' 4 1/2, but the Surveyors should be requested to state if this is so.

See letter



© 2020

Lloyd's Register Foundation

007620-007625-0041