



The attached letter has been received from the Builders enclosing their certificate showing the results of the statutory Test in respect of steering chains fitted on board this vessel, which are satisfactory.

The Builders explain that owing to an oversight the Surveyor was not advised of the testing and was consequently not present.

They point out that the diameter of the chains fitted is in excess of the Rule requirement.

The Builders submit that, in the above circumstances, the chains supplied might be accepted.

The case is submitted for the favourable consideration of the Committee.

 
12-1-34



© 2020

Lloyd's Register
Foundation

007714-007721-0266

It is concluded that solid flying jacks fitted on alternate

12-1-34