

1E

of Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

NAME

Rock

Rpt.

Two  
Sms.

No.

90909  
15261

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

of Engine

Cile Engines

2 S.C.S.A.

4 Cy.  $12\frac{1}{2}$ " -  $18\frac{1}{4}$ "

NHP 109.

of Boilers fitted with forced draught

Mail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }  
approved type

None

No

No

This vessel's machinery appears to have been built in accordance  
the Rules and the approved plans, and it is submitted she is  
able to be classed + LMC 1.34

2.4  
12/1/34.  
AP



© 2020

Lloyd's Register  
Foundation

007714-007721-0289