



## LLOYD'S REGISTER OF SHIPPING

165, HANANOCHO,

No. 362

SHIMONOSEKI, 29th August 1941.

(P. O. Box 26)

TELEGRAMS: "REGISTER," SHIMONOSEKI.  
TELEPHONE: ONE: 2646.

Reference Re

S.

The Secretary,

LONDON.

Dear Sir,


S.S. "SEIZAN MARU"  
Smk. Rpt. No. 2610.

In reply to your classing letter of the 4th July last, I have to say that the H.P. Piston was repaired by part machining off the bottom flange part and shrinking a steel ring on in order to adjust the clearance between the piston and the cylinder wall as shown in the sketch below.

Upon special examination in November last, it was found in efficient condition, however, considered better to examine again at next Annual Survey.

I am, Dear Sir,

Yours faithfully,



Steel ring shrink on.

T. Kumabe  
SURVEYOR TO LLOYD'S REGISTER.Lloyd's Register  
Foundation



H  
R D

THE END

1874

100-100-100

THE DECEMBER

© 2020

Lloyd's Register  
Foundation