

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 19... When handed in at Local Office 19... Port of London
No. in Reg. Book Survey held at 81057 on the Wood, Iron or Steel Sc "NORMANVILLE"
Date, First Survey 1921 No. of Visits 1
Last Survey 1921
TONNAGE: GROSS 1803 Built at South Shields By whom B. Kennoldson & Co
UNDER DECK 1360 Owners Wams & Co
NET 1018 Managers
Owners' Address
(if not already recorded in Appendix to Register Book).
Port belonging to Havre

Surveyed Afloat or in Dry Dock? Name of Dock
WB-Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1636 Port Rou.

(Periodical Surveys, when held, must be reported in detail and notation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Paired or Repaired ...								
Paired or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on feet). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length mean diamr. (on board) size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Standing and Running Rigging
Floors		Transoms Pointers, & Crutches ditto	
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shells ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20) £	Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 20) £	Received by me, 19
Travelling Expenses (if chargeable) £	
Second Surveyor's Fee (if any) £	

Committee's Minute

Character assigned

TUE. 11 MAY 1937

Withdraw class

General Committee

Thursday 20 May 1937

Classing Committee decision

Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register

Mr. Munro.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower

[illegible]