

4 E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "VIRGEN DE LA ESPERANZA"

Rpt.

Bcl. No. 5200

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey


~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH~~

Docking.

The Surveyor reports original main engines and shafting and stern gear removed and new engines, shafting and stern gear fitted.

He also states that a First Entry report will be furnished as soon as possible.

IT IS SUBMITTED action be deferred pending receipt of the First Entry report.



© 2021

Lloyd's Register
Foundation

18. 7. 47.

007881 - 007887 - 0273