

3m, 11, 30.

12 FEB 1940

by Chief Ship Surveyor

received from Chief Ship Surveyor

VESSEL'S NAME "MARIN SANUDO" Rpt. Gen. No. 16059

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to riveting in Nos 2 & 5 double bottom tanks being dealt with.

The Genoa Surveyors now report the vessel placed in dry dock, bottom coated.

Time did not permit ~~that~~ ^{being} the riveting in Nos 2 & 5 D.B. tanks ~~be~~ dealt with at this time. It is stated this will be dealt with at the earliest opportunity.

It is submitted the vessel appears worthy to remain as classed with record of survey 1.40, subject as above.

100A1)-subject etc.
1,40 Gen)

all
9.2.40



© 2020

Lloyd's Register
Foundation

007909-007918-0325

Longitudinal
Transverse
Floors