

8 SEP 1951

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME CHARTERED Rpt. NWC. No. 97791

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

DAMAGE.

Damage through *grabs and cause not stated*

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	3						
Removed and faired or repaired.....							
Faired or repaired in place.....		4					
Other items:-	<i>Vessel placed in dry-dock, bottom coated</i>						


Wear & tear.*Repairs to a shell plate, hatches and minor repairs effected*

It is submitted the vessel is worthy to remain as classed with
record of Survey 8-39.

100 A.1.

8-39 NWC.

The Certificate of Classification to
be endorsed "Cargo battens not
fitted" and the same notation to be
printed in the Register Book.



© 2020

Lloyd's Register
Foundation

007430-007437-0199