



Lloyd's Register of Shipping.

Holbergsgade 11

Copenhagen, K. 26th April, 1948.

RECEIVED

27 APR 1948

ANSO.....

Communications to be addressed
to SURVEYORS
Lloyd's Register of Shipping,
Copenhagen, K.

The Secretary,
Lloyd's Register of Shipping,
London.

Dear Sir,

With reference to your classing letter of the 23rd inst. regarding the S/S "CLARA" we have to state that the fore- and afterpeak spaces and the chainlocker have been examined and that it was not considered necessary to drill the bottom plating in way of cement in No 3.4. and 6 double bottom tanks. ~~then examined.~~

As stated in Rpt. No 12323 the double bottom tanks No 1,2, and 5 have not been examined as they were full of water. No 2 tank is the space ^{forward of} and No 5 tank the space abaft the engine room.

Yours faithfully

G. Buchanan
for H. K. Juhl.
SURVEYOR TO LLOYD'S
REGISTER OF SHIPPING



© 2020


Lloyd's Register
Foundation

008077-008080-0269

REGIS'

1901

Lloyd's Register
Foundation



Noted. $\frac{28}{4}$
48

三