

GEORGE D. LIDGETT  
SHIP AND ENGINEER SURVEYOR  
TELEPHONES { OFFICE NO. 43-624  
RESIDENCE NO. 63-605

CABLES AND TELEGRAMS:  
"GEOLIDGE," WELLINGTON

CODES:  
BENTLEY'S PHRASE & SECOND PHRASE  
LLOYD'S PRIVATE

G.P.O. Box 996

# Lloyd's Register of Shipping


NATHAN'S BUILDINGS,

GREY STREET,

WELLINGTON C.1., N.Z.

14th. February, 1939

REFERENCE  
GDL/BNL.



LETTER No. 2783.

THE SECRETARY,  
LLOYD'S REGISTER OF SHIPPING,  
71 FENCHURCH STREET,  
LONDON. E.C.3.

S

Dear Sir,

## FERRY STEAMER "MURITAI"

I have to/acknowledge receipt with thanks of your letter and enclosure respecting the Ferry Steamer "MURITAI".

The Owners have already been advised that all rivetted seams of the forward boiler must be bared for Special Examination at the next Boiler Survey.


I read with interest your letter to the Eastbourne Borough Council also reference to Mr. Ripley's Report. However, I still maintain from my examination and it is my considered opinion that the cause of this trouble is due to the original fault or at least 90% of it.

I am, Sir,

Yours faithfully,

*George D. Lidgett*

SURVEYOR TO LLOYD'S REGISTER  
WELLINGTON N.Z.



Lloyd's Register  
Foundation



