

Standard mean Sheer [Table Para. 18] 18.05
 Difference..... 6.12 ÷ 4 = 1.53
 § If limited as Para. 18 (f)

Correction
 Round of Beam 7 1/2"

2m.12.20.

EEBOARD REPORT on the

S.S. "Mauritai".

It is submitted the Freeboards given on the accompanying form being those required by the Tables merit approval, for the voyage to New Zealand only, subject to the sides of the vessel being efficiently closed in by wood as shown on the report, the vessel being suitably prepared for the voyage and provided there are no scuffs or other openings fitted through the ship's sides to affect the position of the load line disc.

Mr Shaw, the Society's Senior Surveyor at Glasgow should be requested to join in the survey.

The Surveyors should be informed that the 14" dia. side lights in the Forecastle not fitted with hinged deadlights should be protected with wooden plugs as proposed.

A fee of £6 (being double the usual fee) should be charged as proposed.

5 Plans to return.

	Length.	Length allowed.	Height.
Forecastle.....	54'-0"	54'-0"	7'-0"

008087-008095-0057

Annual Summer Freeboard
 N. A. Winter Freeboard

Correction necessary because clearside amidships, measured)

© 2021
 Lloyd's Register
 Foundation