

"GONCALO VELHO"

The class is subject to the LP column being renewed at the first opportunity and the propeller repaired at the Owners convenience.

A Special Survey became due 8.46 and a BS 6.47.

The vessel now holds the notation of "Laid up pending survey and repairs". The attached cable has now been received from the Lisbon Surveyors.

The proposal is submitted for approval provided a Boiler Survey be held, and the LP column further examined.

L. J.

5.8.48



© 2021

Lloyd's Register
Foundation

008087-008095-0245