

"EMPIRE GRENFELL"

Sld Rpt. No. 33265.

It is submitted the Sunderland Surveyors be informed
it is concluded that the 'tween deck bulkhead next abaft the
collision bulkhead is intact or alternatively if openings were
cut for access that the closing plates have been riveted.



f.c.D.
6.1.42



© 2020

Lloyd's Register
Foundation