

29 NOV 1933

S.S. "FRANCUNION V"

The class is subject to the tank top in engine room being repaired at the next Special Survey and the stern frame, repaired by electric welding 6,31, 3,32 and 2,33, specially examined at the next dry docking.

The 2nd S.S.No. 2 became due 10,32, and a proposal to carry same out within the year of grace was agreed to.

Repairs are required to indented plating etc. on port side forward.

As the year of grace had expired, and the vessel was stated to be laid up indefinitely at Algiers, the Owners were requested to sign the usual undertaking.

A letter has now been received from the Owners stating that the vessel is not trading, but is being used as a depot ship for the storage of oil for bunkering purposes, and that after due consideration it has been decided to allow the class to lapse.

The case is submitted for the consideration of the Committee.

28.11.33



© 2021

Lloyd's Register
Foundation

008129-008136-0014