

1

JACO

DISCLOSED SECTION.

548

Sent to Chief Surveyors

No. ....

Received from Chief Surveyors

VESSEL'S NAME

'JACO'

REPORT

No. -

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

55 due 1,52

In January 1951 the Curacao Surveyors reported both screwshaft cones to be corroded and recommended that the shafts be renewed by 7.51.

The class is also subject to the two outboard engines being uncoupled and in the event of either or both of these engines being used for driving the line shafting, the Society should be advised.

Information was received from the Copenhagen Surveyors in August to the effect that the vessel had been sold to a Venezuelan Owner and the Curacao Surveyor was accordingly requested to ascertain the new Owner's intentions regarding the renewal of the screwshafts.

The Surveyor was, however, unable to contact the Owner either through the Venezuelan Consul or through other agents, in the absence of the Owner's full address. This was subsequently obtained by the Copenhagen Surveyors and the Curacao Surveyor was again requested to endeavour to contact the Owner.

The Curacao Surveyor now states that he has received no reply from the Owner to his subsequent enquiry.

A Special Survey became due in 1.52 and the under mentioned items remain to be examined to complete the Continuous Survey of the machinery. (The hull SS has not been commenced)

The case is submitted for the consideration of the Committee.

To complete the CS: Examine:-

- Auxiliary engines (except after and port forward.)
- Independent pumps.
- Daily service tanks.
- Electrical installation (except Megger test.)



19. 2. 52.

Lloyd's Register Foundation

008158-008167-0059