

22 MAR 1955

nt to Chief Surveyors.....

Received from Chief Surveyors.....

GB

SHIP'S NAME "ENRICHETTO" REPORT No.....

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER~~ SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Signature of Surveyor..... ~~Wick XXX~~

The class is subject to sternframe solepiece (E.W. & reinforced 4,53) and indented shell plates C.2 & I.13 (s.s.) being specially examined at next drydocking, to D.B. tank top plating (p.s.) in No.5 hold being examined and dealt with as necessary at the Special Survey, and to No.1 D.B. tank being examined and dealt with as necessary on arrival at Genoa.

In a letter dated 16.3.55 the Genoa Surveyors advise that the Owners have informed them that as the ship must be classed with the Registro Italiano they have decided to withdraw the class with this Society.

IT IS THEREFORE SUBMITTED the class of this ship be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at Owners' request.

WITHDRAW CLASS and  
INSERT IN R.B.  
(...)



© 2020

Lloyd's Register  
Foundation

008231-008236-0049