

Rpt. Ham. 1575.

"POINT CLEAR"

In the course of a Reclassification Survey, the 3rd deck in Nos.1 & 2 holds has been removed.

The arrangement of webs, stringers and pillars as shown in the report is satisfactory. It is assumed that pillars are fitted at the corners of No.2 hatch as at No.1 hatch, but the Surveyors should be requested to confirm this.

JMB.
2nd January, 1952.

Ad



© 2020

Lloyd's Register
Foundation

008231-008236-0064